








straight flattrack line requirements



flattrack connectors



1




2



Track power supply

3



4



5



Box with power supply

3



4




48V DC

box with the power supply


push to remove

5




mechanical connection


„L” connection




„T” connection





straight connection




wall-ceiling connection










REQUIRED




1




2




3



4



5



6

